HP TippingPoint Product Bulletin

Product Bulletin #1051

Subject: **IPS Resource Affecting Digital Vaccine Installation**

Date of Announcement: **August 11, 2015**

Summary

Due to the recent and expected growth of our new Digital Vaccine filters, some devices may reach a limit while enabling the use of additional filters. Customers running devices with the majority of their filters enabled are likely to encounter this limitation. Customers running the device with security profiles set to the default "Recommended" settings are unlikely to encounter this limitation.

The more filters enabled, the greater the chance of encountering the following error in the system log:

```
<ERR> [NP] <Br0> npRuleStatTableFind: rule stats array has become full.  Cannot
allocate space for a new rule
```

Affected Products and Versions

TOS Version	Impacted Products
3.2.7 and lower	S1200N Security Blade
	S10, S110, S330
	S660N, S1400N, S2500N, S5100N, S6100N
3.6.1 and lower	S10, S110, S330
	S660N, S1400N, S2500N, S5100N, S6100N
	S2600NX, S5200NX, S6200NX, S7100NX, S7500NX

Non-impacted Product and Versions

TOS Version	Description
3.2.8	S10, S110, S330, S660N, S1400N, S2500N, S5100N, S6100N
3.6.2 or later	S10, S110, S330, all N and NX models

Recommended Action

HP TippingPoint recommends that customers with S-Series devices (S10, S110, S330) upgrade to TOS v3.6.4 and customers with N-Platform (S660N, S1400N, S2500N, S5100N, S6100N) or NX-Platform (S2600NX, S5200NX, S6200NX, S7100NX, S7500NX) devices upgrade to TOS v3.8.0.

For questions or technical assistance, on any HP TippingPoint product, contact the HP TippingPoint Technical Assistance Center (TAC).

Thank you,
HP TippingPoint

Support Contact Information:
HP TippingPoint TAC
Toll Free: 866 681 8324 | International: +1 512 681 8324
Email: tippingpoint.support@hp.com