



# End of Sale & End of Life Announcement for S1200N IPS Module

## Product Bulletin #1035

Date of Announcement: March 13<sup>th</sup>, 2014

### Summary

This product bulletin described the end-of-life (EOL) dates for the S1200N IPS Module and associated maintenance options. The last day to order the affected products is June 30<sup>th</sup>, 2014, while quantities last. Customers with active maintenance contracts will continue to receive support from TippingPoint's Technical Assistance Center (TAC) for three years after the end-of-sale date.

### Affected Hardware Products

HP Part Number	Description	EOS Date
JC527A	HP TippingPoint S1200N IPS Module	June 30 <sup>th</sup> , 2014

### Product End-of-Life Dates

Milestone	Definition	Dates
End-of-Life, End-of-Sales Announcement	The date on which HP TippingPoint announces the end of sale and end of life of a product.	March 13 <sup>th</sup> , 2014
End-of-Sale	The last date to order product through TippingPoint point of sale. The product is removed from the price list after this date.	June 30 <sup>th</sup> , 2014
End of 1-year Renewals	The last date to order 1-year maintenance renewals.	June 30 <sup>th</sup> , 2016
End of Support	The last date that support calls will be accepted for the affected product. DV updates and RMA's will no longer be provided or supported on the product.	June 30 <sup>th</sup> , 2017



## Product Migration Options

EOL Part	Replacement Part	Description
S1200N IPS Module (JC527A)	S2600NX (JC874A)	HP TippingPoint S2600NX 3Gbps IPS
	S5200NX (JC824A)	HP TippingPoint S5200NX 5Gbps IPS
	S6200NX (JC873A)	HP TippingPoint S6200NX 10Gbps IPS
	S7100NX (JC644A)	HP TippingPoint S7100NX 15Gbps IPS
	S7500NX (JC872A)	HP TippingPoint S7500NX 20Gbps IPS

© Copyright 2011–2014 Hewlett-Packard Development Company, L.P. The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

Created March 2014